

## Over the Air System Updates

April 28, 2018

### 2018 Accord: Software Update Display Audio/Navigation Available

#### INTRODUCTION


The latest software contains system enhancements and bug fixes for a number of rarely found problems.

#### INSTALLATION DETAILS

**NOTE: For more information on how to do a software update, see System Updates in the online owner's manual or <http://owners.honda.com/vehicles/subscriptions-downloads-updates>**

- Software download will take about 30 minutes via Wi-Fi.
- Download time will vary based upon internet speed.
- Update time is displayed for informational purposes. The vehicle can be used normally even while updates are being downloaded or updated.
- Depending on your vehicle trim, some enhancements/bug fixes may not be available.

**Go to System Updates on the Menu Screen in your Vehicle to Start the Update**



#### NEW SOFTWARE VERSION 18AA-1835-001

NOTE: Your vehicle may or may not contain the information change points listed below, due to the functionality available within your vehicle trim. As well as the Software version level currently installed in your vehicle.

- No GPS detected on Notification tab, due internal system data received at the same time.
- *Bluetooth*® Audio Meta Data sometimes not shown after turning Ignition OFF/ON
- Phonebook Contact not updated, and stays the same as previous device connected.
- HondaLink® Assist Settings shown with English text when settings are set to French mode.
- HondaLink® Assist Settings shown with English text when settings are set to Spanish mode.
- While on a 3-way call, and turning the ignition ON, the Display Audio only shows the call status on the HFL mode top banner.
- While on a call turning the ignition ON, the Display Audio only shows the call status on the HFL mode top banner.
- Paired phone call does not transfer when switching ACC OFF/ON.
- Both ON and OFF buttons are active, in the *Bluetooth*® Option Setting Screen.
- No Driver Distraction is active while pairing a new device.
- *Error* message shown when switching from *Bluetooth*® connection, to Apple CarPlay, when using the same device.

- Display Audio does not show error message when connecting a Phone device, which does not have any music files via USB audio source.
- CarPlay disclaimer screen may be interrupted, immediately after pressing the steering wheel Talk button and activating Siri® Eyes Free Mode.
- Meter screen wording does not fit into the screen for many languages.
- Driver Distraction feature does not work when the Tips are shown on Phone, Favorite Contacts, or Reorder screen.
- Incoming call screen displayed at ACC ON, after an HFT call was rejected at ACC OFF.
- Unable to return to the last screen when turning the ignition OFF/ON while using CarPlay.
- *CarPlay* error message when turning ignition OFF/ON.
- Long Boot Up and/or reset after Ignition ON.
- Audio plays from the center speaker, when receiving a test message and using voice recognition.

**Software Release Note(s) 18AA-1863-001:**

- CarPlay cannot be connected after multiple connections/disconnection.
- Display Audio reboots when operating the shift lever/selector quickly between R (reverse) and D (drive).
- Speed limit sign eliminated from Navigation App.
- **Install Is Complete** displays before the Over the Air process is complete.
- After Over the Air software update and system reboot, system does not go to back into OTA application.