System Updates

The audio system's firmware can be updated with a Wi-Fi connection or with a USB device.

How to Update Wirelessly

Wireless connection mode setup

Passe	Navissike	en e		12:34
S	System	Updates		Settings
		1000		
	- 1	ŝ.	4	
		via Wireless	via USB	

5	Navisation PM			12:34
) 	Change OFF - Turn O	Mode FF vehicle Wi-	FI.	
	Network			~
ï	HotSpot			
	OFF			
2		Save	Cancel	

- 1. Select 🏦
- 2. Select System Updates.
- 3. Select Settings.
- 4. Select Connection Setup.

5. Select Change Mode.

- 6. Select Network, then Save.
 - ► The display returns to the network list.
- Select an access point from the network list, then Connect.
 - If the audio system requires a password, enter a password.

Wireless connection mode setup

If your vehicle has a telematics control unit (TCU), you do not need the wireless connection mode setup.

How to update

When the audio system update is available, the notification is shown on the audio/ information screen. Use the following procedure to update the system.



- 1. Select 🏦 .
- 2. Select System Updates.

Notification

Features

	Generation IV	12:34			
35	Step 2/6	Change Connection			
1	Connection AA	AAA			
8	Software Update is Available				
	Version XXXXX				
	Update size XXX MB				
	XXXXX				
	Downloa	d Now			

- 3. Select via Wireless.
- 4. Select Download Now.
 - ► A notification appears on the screen.



5. Select Install Now or Install while Vehicle OFF.

A notification appears on the screen if the update is successful.

➢How to update

If **Install while Vehicle OFF** is selected and the user turns the vehicle back on after the update has been completed, for 3 to 5 minutes the system will rebuild the applications, during which time the Honda logo will be displayed.

Automatic download settings

Use the following procedure to change to the automatic download setting.



- 1. Select 🟦 .
- 2. Select System Updates.
- 3. Select Settings.
- 4. Select Auto Download.
- 5. Select the access point, then Allow.

■ View an update result

Use the following procedure to confirm the update result.

er Kolasten FV	12:34
>>> Update Result	
🥝 System Update:	Update Success

- 1. Select 🟦 .
- 2. Select System Updates.
- 3. Select Settings.
- 4. Select Update Result.

How to Update with a USB Device

Download the update files from the server

Phone.	Q Naviselke	M		12:34
C	System	Updates		Settings
		1		
		via Wireless	via USB	

Phone	Kasipitan PU		12:34			
S>	Step 2/6					
	Insert USE download https://usi	device int the require b.honda.co	o compute ad softwar m for inst	er and fol e update ructions.	low the lir files. Refe	ik to ir to
		-		_		

- 1. Select 🏦
- 2. Select System Updates.
- 3. Select via USB.
- ► A notification appears on the screen.
- **4.** Connect a USB device into the USB port in the console compartment.
 - The inventory data is copied into the USB device.
 - DSB Ports P. 275
- 5. Remove the USB device from the USB port.
- Connect the USB device into your computer, and then download the update files.
 - Follow the link to download the required software update files. Refer to https://usb.honda.com for instructions.

How to Update with a USB Device

A USB device with a minimum of 8 GB of free space or more is recommended.

Be sure to delete any previous inventory or update files from the USB before starting the USB update process.

Update the audio system



nen	Newsystem TN	12:34				
C	Step 5/6					
×.	Software Update	is Available				
	System may not function and may reboot during installation					
	Version XXXXX					
•	Update size XXX MB					
	Install Now	Install while Vehicle OFF				

- 1. Select 🟦 .
- 2. Select System Updates.
- 3. Select via USB.
 - ► A notification appears on the screen.
- **4.** Connect the USB device with the update files into the USB port.
 - A notification appears on the screen.USB Ports P. 275
- 5. Select Install Now or Install while Vehicle OFF.
 - A notification appears on the screen if the update is successful.

Dpdate the audio system

If **Install while Vehicle OFF** is selected and the user turns the vehicle back on after the update has been completed, for 3 to 5 minutes the system will rebuild the applications, during which time the Honda logo will be displayed.